

System Report Master Display System

Report: B85 Ignition Report

| Timestamp | Feed Pump 1/2/3/4 | Feed Pump Press Psig | Feed Water Temp. | Deaerator - 3 | Deaerator Pressure Psig | Deaerator Water Temp. Deg.F |
|-------------------------|----------------------|----------------------------|---------------------|---------------|-------------------------------|-----------------------------------|
| 13 Dec 2022 05:37:33 | 20470.62 | 23555.0 | 26736.0 | 213.98 | 9.46 | 20.18 |
| 13 Dec 2022 05:38:33 | | | | | | |
| 13 Dec 2022 05:39:33 AM | 0 | 300.2464 | | 3 | 2.86868 | 222.76 |
| 13 Dec 2022 05:40:33 | | | | | | |
| 13 Dec 2022 05:41:33 AM | 0 | 300.4669 | | 3 | 4.27335 | 222.09 |
| 13 Dec 2022 05:42:33 | | | | | | |
| 13 Dec 2022 05:43:33 AM | 0 | 299.8055 | | 3 | 6.63521 | 222.16 |
| 13 Dec 2022 05:44:33 | | | | | | |
| 13 Dec 2022 05:45:33 AM | 0 | 298.4825 | | 3 | 4.86479 | 223.15 |
| 13 Dec 2022 05:46:33 | | | | | | |
| 13 Dec 2022 05:47:33 AM | 0 | 300.3372 | | 3 | 4.97471 | 223.31 |
| 13 Dec 2022 05:48:33 | | | | | | |